EXHIBIT B

Case: 19-30088 Doc# 10441-2 Filed: 03/22/21 Entered: 03/22/21 14:42:57 Page 1 of 2



Invoice

Date Invoice # **Terms Due Date**

8/15/2018

22552d

2/10 Net 30

Phone Number

916-760-8944

9/14/2018

Fax Number

916-760-8970

West Sacramento Ca 95691 Lic. # 935197

4015 Seaport Blvd

Bill To

Ship To

E-mail office@bullseyeleak.com

Web Site

www.bullseyeleak.com

P.O. No.

Technician

Farmers Insurance Exchange PO Box 268994 Oklahoma City, OK 73126-8994

Tax ID # 30-0568016

Dan

1 ux 15 // 00 000010				
Description	Qty	Rate	Amount	
Claim# 3011311133-1				
1814 Broadway St				
Vallejo, CA 94589				
Upon arrival I met with the homeowner.				
Area of concern: I was told sewage surfaced soon after PG&E had performed work				
out front of the business. The owner had hired a plumber who could not clear the line.				
First point of camera entry: Clean-out				
First camera run: There was no visibility during the inspection as the line was. It was				
filled with standing sewage. I ran the camera approximately 60 ft when I found an obstruction I could not pass. I located the obstruction at the edge of the PG&E trench.				
It appears that the sewer line has been crushed by trade damage. The sewer line is				
approximately 4' deep and the gas trench was likely at a higher elevation so they did not know there was a conflict during their work.				
Anomaly found: Yes				
Anomaly location: at PG&E trench on Broadway side of the building.				
Approximate anomaly depth: 4 feet Demarcation of anomaly: Paint				
Note: Due to poor visibility and/or limitations of the inspection equipment, we cannot				
determine pipe material with 100% accuracy and do not guarantee our findings with				
regard to pipe material. insurance commercial leak detection		400.00	400.00	
extra hour		175.00	175.00	

If Bullseye Leak Detection, Inc. is required to return for an additional inspection or leak detection, it will be considered above and beyond the scope of this invoice and will be billed at the current prevailing rate. All markings are good for 30 days and only on utilities marked by Bullseye Leak Detection, Inc. Payment is due upon completion of work unless otherwise agreed to in writing and authorized by an officer of Bullseye Leak Detection, Inc.

Thank you for your business.

Total	\$575.00
Payments/Credits	\$0.00
Balance Due	\$575.00

Case: 19-30088 Doc# 10441-2 Filed: 03/22/21 Entered: 03/22/21 14:42:57 PROMINE B